Okuma America Corporation

Okuma Machine Alert System

Release Notes

Document No.: S5061-006-05

Revision History

Date	Version	Description	Author
10/22/2013	S5061-006-00	Public release Version 1.4.3.0	Thanh Huynh
03/14/2014	S5061-006-01	Public release Version 1.4.4.0	Linh Huynh
08/05/2014	S5061-006-02	Public release Version 1.4.5.0	Linh Huynh
12/11/2014	S5061-006-03	Public release Version 1.4.6.0	Linh Huynh
05/28/2015	S5061-006-04	Public release Version 1.4.7.0	Linh Huynh
09/24/2021	S5061-006-05	Public release Version 1.5.0.0	Linh Huynh

Table of Contents

Release Notes for Okuma Machine Alert System

1. Introduction

1.1 Disclaimer of Warranty

Okuma America Corporation makes no representations or warranties, either expressed or implied, by or with respect to anything in this document, and shall not be liable for any implied warranties of merchantability or fitness for a particular purpose or for any indirect, special or consequential damages.

1.2 Purpose

The purpose of the *Release Notes* document is to communicate major new features and changes in this release of the Okuma Machine Alert System option. It also documents known problems and workarounds.

1.3 Scope

This document describes the release of Okuma Machine Alert System version 1.5.0.0

1.4 References

- OKUMA Startup Service

2. About This Release

2.1 Prerequisite Software

This release of this application is required to include:

- THINC-API release 1.12.1.0 for Lathe and Machining Center

- THINC-API release 1.21.1.0 for Grinder

- Start-up Service version 5.0.0.0 or newer.

2.2 License

This application requires no license.

2.3 Machine Model

This release supports OKUMA OSP-P100-II/P200/P300 control. This public release can be installed to run on PC with Windows XP x86 SP3/Windows 7 x86, and Windows 10 x86/64.

Please contact your local distributor service department if you experience any difficulties with installing the software or using the system.

2.4 Features

2.4.1 New

The Machine Alert System can now support Windows 10 x64 and can send email through network using TLS protocol.

2.4.2 Change

- The application can support different character to be the separator for the alarm message field. The default character is an equal sign, '='.
- Remove the option of minimizing the Windows TaskBar checkbox in the System configuration.
- Add file extension to the attached image

3. Defect

None